

# SILEC CONSULTING PTY LTD

10304/7 Wharf Street  
HAMILTON Q 4007  
Ph: 0413709303

## SITE INSPECTION REPORT FOR SLEEPER WALLS

Builder	CONCRIB	Date issued	2/11/20.
Civil Contractor	PENSAR	No. of Pages	1
Job Number	19546	Project Size	500m <sup>2</sup>
Address	420 STA. PINE RD. EVERTON PK.		

ITEM INSPECTED			
FOUNDATION INSPECTION		FINAL WALL CONSTRUCTION	
1	DESIGN CERTIFICATION/DRAWINGS ON SITE	Y	13 WALL VERTICALITY OR BATTER
2	DO RETAINED HEIGHTS REFLECT DESIGN/DRAWINGS	Y	14 WALL ALIGNMENT
3	CORRECT PIER DIAMETERS	Y	15 AG PIPE OUTLETS
4	CORRECT PIER DEPTHS	Y	16 BEAM PURCHASE ON UC/UB FLANGE
5	CORRECT UC/UB/CONCRETE PIER SIZES	Y	17 DO LIVE & DEAD LOAD CONDITIONS ON TOP, REFLECT DESIGN
6	HAVE SERVICE TRENCHES BEEN LOCATED/TREATED CORRECTLY	Y	18 HAVE CUT ENDS OF BEAMS HAD EPOXY TREATMENT
7	CORRECT CONCRETE CLASS ORDERED	Y	19 FOR STEPPED FOOTINGS IS PANEL NOTCHING CORRECT
8	IF CAGE REQUIRED, CORRECT PLACEMENT//COVER//SIZE <i>EXT BARS</i>	Y	20 FOR TERRACE WALLS IS TERRACE WIDTH CORRECT
9	DO BATTERS IN FRONT & TOP OF WALL MEET DESIGN	Y	21 GEOFABRIC INSTALLED & AG PIPES WITH OUTLETS
10	SUFFICIENT VOID BEHIND WALL FOR GRAVEL DRAINAGE	Y	
11	RETAINED MATERIAL DESCRIPTION: <i>CONTROLLED FILL</i>		
12	FOUNDING MATERIAL DESCRIPTION: <i>STIFF NATURAL CLAY</i>		

<b>AREA/LOTS/ADDRESS INSPECTED</b>	<i>PIER FOUNDATIONS TO TOP TERRACE WALL LOT 81</i>
------------------------------------	--

<b>RECTIFICATION REQUIRED</b>
-------------------------------

Inspected By: <i>M. SILEC</i>	Received By: <i>M. BROAD</i>
Email:	Representing: <i>CONCRIB</i>
Signed: <i>M. Silec</i>	Signed:
Reinspection required? <i>N.</i>	Invoice Required? <i>N.</i>
Report to Builder? <i>Y</i>	

VERIFICATION BY RPEQ: *M. Silec* No: 19129 DATE: *2/11/20.*